


VOLUNDR





Today

What's in the future?

Just soldering

Programing is possible

Volundr soldering workshop



Components, a basic reminder



Preparation



Making a good soldering joint



Common soldering problems




Components

a basic reminder


LEDs


- Diodes, but different




Adressable LEDS

APA106
深圳秀美科技








Elco



Bipolair

Capacitors



Preparation







Clean the tip on a
wet sponge




Apply a small amount of solder to the tip and wipe again to tin the tip. You should have a thin, shiny layer of molten solder on the tip of your iron.



Make sure that the joint is clean. Dirt, oxidation and oily fingerprints can prevent the solder from wetting the solder-pad to create a solid joint.




Immobilize the joint. The parts being joined must not move during the soldering process. If there is any movement as the molten solder is solidifying, you will end up with an unreliable 'cold joint'.



Steady the board



Making a good
soldering joint




Heat the joint with the tip of the iron. Be sure to heat both the solder pad and the component lead or pin.



Apply the solder. Touch the end of the solder to the joint so that it contacts both the solder pad and the component lead or pin. It should melt and flow smoothly onto both the pin and the pad.

Let It flow. Keep heating the solder and allow it to flow into the joint. It should fill the hole and flow smoothly onto both the solder pad and the pin or component lead.













Trim the lead. Use your diagonal cutters to trim the lead close to the board

Common soldering problems





The ideal solder joint






A disturbed joint.
Surface of the joint frosted, crystalline or rough.
Reheat and allow the joint to cool undisturbed

Cold joint.
The solder did not melt completely and forms a lumpy surface. Repair by reheating the joint and drawing off excess solder






Overheated joint
residue of burnt flux will accumulate.
Fixed by cleaning and careful scraping of
the burnt flux.



Insufficient wetting
of the pad.
Can be repaired by
placing the tip of
the soldering iron
at the base of the
joint.

Insufficient wetting of the
pin.
Can be repaired by reheating
the pin.





Solder starved.
Can be repaired by reheating
and applying more solder

Too much solder.
Can be repaired by reheating
and drawing off some of the
excess solder.





Untrimmed leads. Leads that are too long are potential short circuits. Repair by trimming all leads to just at the top of the solder joint



Solder bridge.
Repair by drawing off excess
solder and prevent by using
only enough solder to make
a good joint.

4 last tips



Work neat



Work Secure



Work methodical



Work from the floor up



Good luck !!!